

SEE OUR VIDEOS AT [PATIENTCOMFORTSYSTEMS.COM](http://PATIENTCOMFORTSYSTEMS.COM)

## THESE CONTAMINATED MRI TABLE PADS VIOLATE CDC AND JACHO INFECTION CONTROL STANDARDS



TORN AND CONTAMINATED TABLE PADS FROM A CHILDREN'S HOSPITAL

### DON'T LET YOUR TORN AND CONTAMINATED TABLE PADS AND POSITIONERS KEEP YOU FROM PASSING YOUR NEXT INSPECTION

- The Center for Disease Control states that pads that are torn and frayed are unacceptable and must be replaced. It is not possible to adequately clean them.
- Be prepared for your next safety inspection.
- Permanent antimicrobial agent incorporated into both the covering fabrics and visco-elastic foam core.
- Safe - Flammability compliant to CTB 133 standards and provides easier movement for positioning.
- Cover fabrics are moisture impervious, latex free and can be cleaned with any standard approved hospital disinfectant.
- Sewn with coated nylon thread seams to protect the pressure managing visco-elastic foam core from body fluids and biological contamination.

### REPLACE YOUR TORN, FRAYED AND CONTAMINATED TABLE PADS WITH PATIENT COMFORT SYSTEMS ADVANCED PAD SYSTEMS WITH ANTIMICROBIALS BUILT INTO THE PADS



THESE PATIENT COMFORT SYSTEMS PADS ARE 2+ YEARS OLD! WHICH PADS DO YOU WANT YOUR PATIENTS ON?

For a free sample, call  
**(866) 943-7727**  
[PatientComfortSystems.com](http://PatientComfortSystems.com)



*Dedicated To Patient Comfort And Safety*